

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

DE888
SE
> 1
1.175 mi.
6205 ft.

LAMSON CORP.
LAMSON STREET
SYRACUSE, NY

Site 12 of 13 in cluster DE

NY Spills S102164869
N/A

Relative:
Higher

Actual:
437 ft.

SPILLS:

Spill Number/Closed Date: 9107363 / 1996-09-30
Facility ID: 9107363
Facility Type: ER
DER Facility ID: 152156
Site ID: 181451
DEC Region: 7
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 3415
Spill Date: 1991-10-08
Investigator: CFMANNES
Referred To: Not reported
Reported to Dept: 1991-10-09
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1991-10-09
Spill Record Last Update: 1996-09-30
Spiller Name: Not reported
Spiller Company: LAMSON
Spiller Address: LAMSON ST.
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
CM 10/10/91: PRODUCT SPILLED-TRIM SOL (WATER MISCIBLE CUTTING AND
GRINDING FLUID OWNER TO SAMPLE SOIL BY EPA 8020,8240,8270,413.3,DOH
310-13,TCLP METALS & PCB'S. 11/08/91: RECIEVED ASSESSMENT FROM SOIL
SAMPLES. INTEX PROPOSED SOIL SAMPLING PROGRAM TO DEFINE THE EXTENT OF
THE CONTAMINATION IN REPORT OF 11/5/91. REQUESTED SCHEDULE FROM
CONSULTANT. 09/28/95: This is additional information about material
spilled from the translation of the old spill file: SYNTHTIC
LUBRICANT."
Remarks: "MACHINERY FAILURE CAUSED RELEASE OF PRODUCT. NORTHEASTERN ENV.
CLEANING UP;7 CU.YDS OF CONTAMINATED SOIL WAS EXCAVATED WHEN FLUID
ESCAPED FROM THE BLDG. UNDER THE DOOR. SOIL IN ROLL-OFF UNTIL
ANALYSIS"

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

DE823
SE
> 1
1.126 mi.
5943 ft.

LAMSON ST. PARKING LOT
END OF LAMSON ST
SYRACUSE, NY 13206

NY Spills S107788964
N/A

Site 10 of 13 in cluster DE

Relative:
Higher

Actual:
434 ft.

SPILLS:

Spill Number/Closed Date: 0650201 / 2007-12-05
Facility ID: 0650201
Facility Type: ER
DER Facility ID: 313920
Site ID: 363738
DEC Region: 7
Spill Cause: Deliberate
Spill Class: B1
SWIS: 3415
Spill Date: 2006-05-09
Investigator: KCKemp
Referred To: Not reported
Reported to Dept: 2006-05-09
CID: Not reported
Water Affected: NONE
Spill Source: Commercial/Industrial
Spill Notifier: Affected Persons
Cleanup Ceased: 2007-11-30
Cleanup Meets Std: True
Last Inspection: 2006-05-09
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2006-05-10
Spill Record Last Update: 2007-12-05
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: ECI JAMES BOYLAN
DEC Memo: "(13) 5-gallon metal pails of used solvent / paint thinner (2)
15-gallon plastic totes of used solvent / paint thinner Abandoned on
edge of parking lot sometime between 1700 5/8/06 and 0600 5/9/06. No
materials spilled, but some containers lacking caps. Next to
residential area. Discovered by property tenant upon start of
business 5/9/06 and reported to DEC TIPPS Line. Inv. Boylan contacted
RSE Brazell, who arranged for containment and removal. Op-tech
called, overpacked, and removed to their site for characterization
and hold as evidence. DEC Boylan to Ok final disposal. Property where
dumping occurred owned by City of Syracuse. 5-22-2006 - USEPA ID #
NYP 000 960 286. Report eDoc'd 5-22-2006 - Received Flashpoint test
results - all flashed at room temp with no heating or agitation.
Report eDoc'd"

Remarks: "(13) 5-gallon metal pails of used solvent / paint thinner (2)
15-gallon plastic totes of used solvent / paint thinner Abandoned on
edge of parking lot sometime between 1700 5/8 and 0600 5/9. No
materials spilled, but some containers lacking caps. Next to
residential area."

All Materials:

Site ID: 363738
Operable Unit ID: 1121801
Operable Unit: 01

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material ID: 2111280
Material Code: 1139A
Material Name: paint solvents
Case No.: Not reported
Material FA: Other
Quantity: 95.00
Units: G
Recovered: 95.00
Oxygenate: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DE889
SE
> 1
1.175 mi.
6205 ft.
LAMSON CORPORATION
LAMSON STREET
SYRACUSE, NY 13221
Site 13 of 13 in cluster DE

NY AST
U003077688
N/A

Relative:
Higher

AST:

Actual:
437 ft.

Region: STATE
DEC Region: 7
Site Status: Unregulated/Closed
Facility Id: 7-004960
Program Type: PBS
UTM X: 410448.59898
UTM Y: 4769086.08932
Expiration Date: N/A
Site Type: Unknown

Affiliation Records:

Site Id: 43902
Affiliation Type: Facility Owner
Company Name: LAMSOM CORPORATION
Contact Type: Not reported
Contact Name: Not reported
Address1: LAMSON STREET
Address2: Not reported
City: SYRACUSE
State: NY
Zip Code: 13221
Country Code: 001
Phone: (315) 432-5500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 43902
Affiliation Type: Mail Contact
Company Name: LAMSOM CORPORATION
Contact Type: Not reported
Contact Name: Not reported
Address1: LAMSON STREET
Address2: Not reported
City: SYRACUSE
State: NY
Zip Code: 13221
Country Code: 001
Phone: (315) 432-5500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 43902
Affiliation Type: Facility Operator
Company Name: LAMSON CORPORATION
Contact Type: Not reported
Contact Name: LAMSON CORPORATION
Address1: Not reported
Address2: Not reported
City: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (315) 432-5500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 43902
Affiliation Type: Emergency Contact
Company Name: LAMSOM CORPORATION
Contact Type: Not reported
Contact Name: DOMINIC FORTUNO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (315) 437-7726
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 003
Tank Id: 125889
Material Code: 0009
Common Name of Substance: Gasoline

Equipment Records:

G00 - Tank Secondary Containment - None
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.

Tank Type: Steel/Carbon Steel/Iron

Tank Status: In Service
Pipe Model: Not reported
Install Date: 04/01/1975
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT

Last Modified: 04/14/2017
Material Name: gasoline

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Tank Number: 004
Tank Id: 125890
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

G00 - Tank Secondary Containment - None
J01 - Dispenser - Pressurized Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.

Tank Type: Steel/Carbon Steel/Iron

Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/01/1976
Capacity Gallons: 175
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017
Material Name: diesel

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

985
SE
> 1
1.243 mi.
6562 ft.

MITTEN FLUIDPOWER INC
1 LAMSON ST
SYRACUSE, NY 13206

RCRA-CESQG
NY LTANKS
FINDS
ECHO
NY MANIFEST

1000384242
NYD004522462

Relative:
Higher

Actual:
455 ft.

RCRA-CESQG:

Date form received by agency: 01/01/2007

Facility name: MITTEN FLUIDPOWER INC

Facility address: 1 LAMSON ST
SYRACUSE, NY 13206

EPA ID: NYD004522462

Mailing address: LAMSON ST
SYRACUSE, NY 13206

Contact: RYAN C CARTWRGHT

Contact address: LAMSON ST
SYRACUSE, NY 13206

Contact country: US

Contact telephone: 315-701-4146

Contact email: Not reported

EPA Region: 02

Land type: Facility is not located on Indian land. Additional information is not known.

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: MITTEN MFG INC
Owner/operator address: 1 LAMSON ST
SYRACUSE, NY 13206

Owner/operator country: US

Owner/operator telephone: 315-437-7563

Owner/operator email: Not reported

Owner/operator fax: Not reported

Owner/operator extension: Not reported

Legal status: Private

Owner/Operator Type: Owner

Owner/Op start date: Not reported

Owner/Op end date: Not reported

Owner/operator name: MITTEN MFG INC
Owner/operator address: 1 LAMSON ST
SYRACUSE, NY 13206

Owner/operator country: US

Owner/operator telephone: 315-437-7563

Owner/operator email: Not reported

Owner/operator fax: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: MITTEN FLUIDPOWER INC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 05/28/2002
Site name: MITTEN FLUIDPOWER INC
Classification: Large Quantity Generator

Date form received by agency: 01/01/2001
Site name: LAMSON/GARDNER DENVER
Classification: Large Quantity Generator

Date form received by agency: 06/30/2000
Site name: MITTEN MANUFACTURING INC
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F017
. Waste name: Not Defined

Date form received by agency: 07/14/1999
Site name: MITTEN MANUFACTURING INC
Classification: Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 11/04/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 12/17/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 05/16/1986
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

LTANKS:

Spill Number/Closed Date: 8603776 / 1987-06-04
Facility ID: 8603776
Site ID: 308318
Spill Date: 1986-08-15
Spill Cause: Tank Test Failure

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: 1987-06-04
SWIS: 3415
Investigator: UNASSIGNED
Referred To: Not reported
Reported to Dept: 1986-09-09
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: Not reported
Spill Record Last Update: 2003-12-02
Spiller Name: Not reported
Spiller Company: LAMSON CORP.
Spiller Address: LAMSON ST.
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 7
DER Facility ID: 152156
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was /
/ : ATLANTIC TESTING LAB DID TANK AUDITOR METHOD. "
Remarks: "#1 TANK - .57 GALS/HR LOSS AT 125 3/4 LEVEL; SYSTEM 1.17 GALS/HR.
AT151 1/4 #2 TANK - .638 GALS/HR AT LEVEL 126; SYSTEM 1.33 GALS/HR"

All Materials:
Site ID: 308318
Operable Unit ID: 900653
Operable Unit: 01
Material ID: 476589
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

FINDS:

Registry ID: 110009465694

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000384242
Registry ID: 110009465694
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110009465694>

NY MANIFEST:

Country: USA
EPA ID: NYD004522462
Facility Status: Not reported
Location Address 1: 1 LAMSON ST

Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: SYRACUSE
Location State: NY
Location Zip: 13206
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYD004522462
Mailing Name: MITTEN FLUID POWER
Mailing Contact: N/S
Mailing Address 1: 5960 COURT ST ES
Mailing Address 2: Not reported
Mailing City: SYRACUSE
Mailing State: NY
Mailing Zip: 13206
Mailing Zip 4: 1706
Mailing Country: USA
Mailing Phone: N/S

NY MANIFEST:

Document ID: NYG2880045
Manifest Status: Not reported
seq: 01
Year: 2003
Trans1 State ID: 47313JB
Trans2 State ID: Not reported
Generator Ship Date: 09/09/2003
Trans1 Recv Date: 09/09/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/09/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD004522462
Trans1 EPA ID: NYD013277454
Trans2 EPA ID: Not reported
TSDF ID 1: NYD013277454
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: F005 - UNKNOWN
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00605
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 011
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00

[Click this hyperlink](#) while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EQ1075
SE
> 1
1.309 mi.
6913 ft.

MITTEN MANUFACTURING
1 LAMSON ST
SYRACUSE, NY

NY Spills S106009816
N/A

Site 1 of 5 in cluster EQ

Relative:
Higher

Actual:
480 ft.

SPILLS:

Spill Number/Closed Date: 0209141 / 2003-10-23
Facility ID: 0209141
Facility Type: ER
DER Facility ID: 251561
Site ID: 311859
DEC Region: 7
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 3415
Spill Date: 2002-12-05
Investigator: MENASH
Referred To: Not reported
Reported to Dept: 2002-12-05
CID: 365
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False

UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2002-12-05
Spill Record Last Update: 2003-10-23
Spiller Name: KEVIN KERSEY
Spiller Company: MITTEN MANUFACTURING
Spiller Address: 1 LAMSON ST
Spiller Company: 001
Contact Name: KEVIN KERSEY
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
MN SEE SPILL # 02-60065"
Remarks: "frozen valve on a tank caused it to overfill - op tech was called to
come in & evaluate situation"

All Materials:

Site ID: 311859
Operable Unit ID: 860534
Operable Unit: 01
Material ID: 565799
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 100.00
Units: G
Recovered: 100.00
Oxygenate: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EQ1096
SE
> 1
1.339 mi.
7070 ft.
LAMSON CORPORATION
LAMSON STREET
SYRACUSE, NY 13221
Site 5 of 5 in cluster EQ

NY UST **U004079623**
N/A

Relative:
Higher

UST:

Actual:
486 ft.

Id/Status: 7-004960 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 7
Expiration Date: N/A
UTM X: 410448.59898
UTM Y: 4769086.08932
Site Type: Unknown

Affiliation Records:

Site Id: 43902
Affiliation Type: Facility Owner
Company Name: LAMSOM CORPORATION
Contact Type: Not reported
Contact Name: Not reported
Address1: LAMSON STREET
Address2: Not reported
City: SYRACUSE
State: NY
Zip Code: 13221
Country Code: 001
Phone: (315) 432-5500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 43902
Affiliation Type: Mail Contact
Company Name: LAMSOM CORPORATION
Contact Type: Not reported
Contact Name: Not reported
Address1: LAMSON STREET
Address2: Not reported
City: SYRACUSE
State: NY
Zip Code: 13221
Country Code: 001
Phone: (315) 432-5500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 43902
Affiliation Type: Facility Operator
Company Name: LAMSON CORPORATION
Contact Type: Not reported
Contact Name: LAMSON CORPORATION
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Zip Code: Not reported
Country Code: 001
Phone: (315) 432-5500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 43902
Affiliation Type: Emergency Contact
Company Name: LAMSOM CORPORATION
Contact Type: Not reported
Contact Name: DOMINIC FORTUNO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (315) 437-7726
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank ID: 125887
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 20000
Install Date: 11/01/1973
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None

J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Tank Number: 002
Tank ID: 125888
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 20000
Install Date: 11/01/1973
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None